

MATERIAL SAFETY DATA SHEET

CHROMATE INDUSTRIAL CORPORATION®

EMERGENCY Call Chemtrec day/night: 1-800-424-9300

FOR CHEMICAL

100 DaVinci Drive, Bohemia, New York 11716 • 888-567-2206 • www.chromate.com

1. CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NAME: Auralloy 810 Self-Fluxing, Non-Fuming Steel Wire

AURALLOY PART NUMBER: 8760-8762

PRODUCT TYPE: Welding Wires for MIG, TIG and SAW

CHEMICAL FAMILY: N/A

DATE PREPARED: February 2, 1999

CHROMATE INDUSTRIAL CORPORATION

100 DaVinci Drive, Bohemia, NY 11716 • (888) 567-2206

2. COMPOSITION / INFORMATION ON INGREDIENTS

CHEMICALNAME	% BY WEIGHT	OSHA PEL	ACGIHTLV	STEL	CAS#
Iron	90-99	5 mg/m ³	10 mg/m³ (as Fe203)	N/D	7439-89-6
Manganese*	1-5	5 mg/m ³	1 mg/m³	N/D	7439-96-5
Silicon	.1 - 1.0	5 mg/m³ (as SiO₂)	3 mg/m³ (as Si0 ₂)	N/D	7440-21-3

3. HAZARDS IDENTIFICATION

PRIMARY ROUTES OF ENTRY: Inhalation of welding fumes

EFFECTS OF OVEREXPOSURE:

INHALATION: Welding fumes and gases can be dangerous to your health. Pre-existing respiratory or allergic conditions may be

aggravated in some individuals.

SKIN CONTACT: Arc rays can burn skin. Electric shock can kill.

EYE CONTACT: Arc rays can injure eyes.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: Short-term (acute) overexposure to welding fumes may result in discomfort such as dizziness, nausea or dryness or irritation of nose, throat or eyes, tightness in chest, fever and allergic reactions (see Section 7).

CHRONIC HEALTH HAZARDS: Long-term (chronic) overexposure to welding fumes may lead to siderosis (iron deposits in the lungs) and is believed by some investigators to affect pulmonary function. Electric shock can kill.

4. FIRST AID MEASURES

EMERGENCY FIRST AID PROCEDURES:

INHALATION: Remove to fresh air, obtain medical attention. Employ first aid techniques recommended by American Red Cross.

INGESTION: Call for medical aid. Employ first aid techniques recommended by American Red Cross. SKIN CONTACT: Call for medical aid. Employ first aid techniques recommended by American Red Cross.

EYE CONTACT: Call for medical aid. Employ first aid techniques recommended by American Red Cross.

5. FIRE FIGHTING MEASURES

FLASH POINT (METHOD USE): Nonflammable FLAMMABLE LIMITS: LEL N/A UEL N/A

EXTINGUISHING MEDIA: N/A

FIRE FIGHTING PROCEDURES: Welding arc and sparks can ignite combustibles. Refer to American National Standard Z49.1 for fire

prevention during the use of welding and allied procedures.

UNUSUAL AND EXPLOSION HAZARDS: No data available

6. ACCIDENTIAL RELEASE MEASURES

SPILLS OR LEAKS: No data available

7. HANDLING AND STORAGE

SPECIAL PRECAUTIONS: Read and understand the manufacturer's instructions and the precautionary label on this product. See American National Standard Z-49.1, Safety in Welding and cutting, published by the American Welding Society, P.O. Box 31040, Miami Fl 33135 and OSHA Publication 2206 (29CFR 1910), U.S. Government Printing Office, Washington D.C. 20402 for more details.

^{*} An asterisk (*) indicates the toxic chemicals subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-to-Know Act of 1986 and 40 CFR 372.

EXPOSURE CONTROLS / PERSONAL PROTECTION

PRECAUTIONS TO BE TAKEN: Read and understand the manufacturer's instructions and the precautionary label on this product. Use exhaust system to clear welding fumes. Make sure that inhaled air does not contain fume constituents above permissible exposure levels. NOTE: Other precautions for additional safety information on welding and cutting, see American Standard Z-49.1-1s, Safety in Welding and Cutting, and the Welding Handbook, Vol. 1, Chapter 9, Safe Practices in Welding and Cutting, both available from American Welding Society, Inc., 550 N.W. LeJeune Road, P.O. Box 351040, Miami FL 33135, Tel. 305-443-9353.

RESPIRATORY: Use respirable fume respirable or air supplied respirator when welding in a confined space or where local exhaust or ventilation does not keep exposure below the recommended exposure limit.

SKIN PROTECTION: Wear hand, head and body protection which help to prevent injury from radiation, sparks and electrical shock. See ANSI Z-49.1. At a minimum, this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hats, shoulder protection, as well as dark substantial clothing. Train the welder not to touch live electrical parts and to insulate himself from work and ground.

EYE PROTECTION: Wear helmet or use face shield with filter lens. Provide protect screens and flash googles, if necessary, to shield others. As a rule of thumb, start with a shade that is too dark to see the weld zone. Then go to the next lighter shade which gives sufficient view of the weld zone.

VENTILATION: Use enough ventilation, local exhaust at the arc, or both to keep the fumes and gases from the worker's breathing zone and general area. Train the welder to keep his head out of the fumes.

PHYSICAL AND CHEMICAL PROPERTIES

BOILING POINT: N/A PRODUCT WEIGHT: N/D VAPOR DENSITY (AIR = 1): N/A SPECIFIC GRAVITY (H₂O = 1): N/D

SOLUBILITY IN WATER: Not Soluble MELTING POINT: N/D PERCENT VOLATILE BY VOLUME: N/A

pH: N/A

VOLATILE WEIGHT: N/A EVAPORATION RATE: N/A

APPEARANCE & ODOR: Solid wire or rod coated with flux for welding process. **VOLATILE COMPONENTS: N/A** FORM: Solid

10. STABILITY AND REACTIVITY

STABILITY: Stable CONDITIONS TO AVOID: None, unless otherwise specified.

HAZARDOUS POLYMERIZATION: SEE ATTACHED SUPPLEMENT

INCOMPATIBILITY (MATERIALS TO AVOID): None

HAZARDOUS DECOMPOSITION OR BYPRODUCTS: SEE ATTACHED SUPPLEMENT

11. TOXICOLOGICAL INFORMATION

EYE: No data available. SKIN: No data available. INGESTION: No data available. INHALATION: No data available.

SUBCHRONIC: No data available. CHRONIC CARCINOGENICITY: NTP: Not Listed IARC MONOGRAPH: Not Listed OSHA REGULATED: Not Regulated

TERATOLOGY: No data available. REPRODUCTION: No data available. MUTAGENICITY: No data available.

12. ECOLOGICAL INFORMATION

ECOTOXICOLOGICAL INFORMATION: No data available. CHEMICAL FATE INFORMATION: No data available.

13. DISPOSAL CONSIDERATIONS

RCRA HAZARD CLASS: No data available

WASTE DISPOSAL METHOD: Prevent waste from contaminating surrounding environment. Discard any product residue disposable container or liner in an environmentally acceptable manner, in full compliance with Federal, State and Local regulations.

14. TRANSPORT INFORMATION

TRANSPORTATION REQUIREMENTS (49CFR172-101)

D.O.T. CLASSIFICATION: Not regulated D.O.T. SHIPPING NAME: Not regulated

15. REGULATORY INFORMATION

EXPOSURE LIMITS: No data available.

16. OTHER INFORMATION

The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of these data or the results to be obtained from the use thereof. Vendor assumes no responsibility for injury to vendee or third persons proximately caused by the material if reasonable safety procedures are not adhered to as stipulated in this MSDS. Additionally, vendor assumes no responsibility for injury to vendee or third persons proximately caused by abnormal use of the material even if reasonable safety procedures are followed. Furthermore, vendee assumes the risk in his use of the material.

N/D — NOT DETERMINED N/A — NOT APPLICABLE N/R — NOT REGULATED